#### United States of America

### Department of Transportation — Federal Aviation Administration

# Supplemental Type Certificate

Number SA7239SW-D

This certificate, issued to

Dassault Falcon Jet P.O. Box 967 Little Rock, Arkansas 72203

certifies that the change in the type design for the following product with the limitations and conditions

therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation

Regulations.

Original Product - Type Certificate Number:

A46EU

**Dassault Aviation** 

Model:

Mystere - Falcon 900

Description of Type Design Change:

Installation of the Emergency Power Supply System in accordance with Drawing List Report No. F90-01036, Revision E dated 11-3-2000, or later FAA approved revision.

#### See Sheet 2

Limitations and Conditions:

Compatibility of this modification with other previously approved modifications must be determined by the installer.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application:

March 25, 1988

Dute reissued:

Date of issuance:

August 4, 1988

Date amended :

1-24-94, 5-12-00, 11-8-00 Rev. 3

By direction of the Administrator

Andrew A. Boersma

DAS8SW COORDINATOR

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

#### United States of America

## Department of Transportation—Jederal Aviation Administration

# Supplemental Type Certificate

(Continuation Sheet)

Number SA7239SW-D

### Description of Type Design Change:

- 1) FAA Approved Airplane Flight Manual Supplement, Report No. 36053-1, Revision A dated 1-24-94, or later FAA approved revision, is required (when F90-01036-501, -503, or -505 installation is used)
- 2) Airplane Maintenance Manual Supplement, Report No. 36597, Revision NC dated 9-23-97, or later FAA approved revision, is required (when F90-01036-503 installation is used)
- Airplane Maintenance Manual Supplement, Report No. 36606, Revision A dated 5-4-00, or later FAA approved revision, is required (when F90-01036-505 installation is used)

INSTRUCTIONS: The transfer endorsement below may be used to notify the appropriate FAA Regional Office of the transfer of this Supplemental Type Certificate. The FAA will reissue the certificate in the name of the transferee and forward it to him. TRANSFER ENDORSEMENT Transfer the ownership of Supplemental Type Certificate Number to (Name of transferee)\_\_\_\_\_\_ (Address of transferee) \_\_\_\_\_\_(Number and street) (City, State, and ZIP code) from (Name of grantor) (Print or type) (Address of grantor) (.Number and street) (City, State, and ZIP code) Extent of Authority (if licensing agreement):

Date of Transfer:

Signature of grantor (In ink):